Manual Supplement

Manual Title: Print Date: Revision/Date: 752A May 1983 1, 4/84 Supplement Issue: Issue Date:

6 6/99

Page Count:

8

This supplement contains information necessary to ensure the accuracy of the above manual. Enter the corrections in the manual if either one of the following conditions exist:

- 1. The revision letter stamped on the indicated PCA is equal to or higher than that given with each change.
- 2. No revision letter is indicated at the beginning of the change.

752A Manual Supplement

Change #1

On page 4-2, add the following sentence to the end of paragraph 4-8:

The 752A must be returned to the factory for this service.

On page 4-11, following paragraph 4-47, add:

Note

Problems involving shifts in resistor values or unstableresistor values that can not be compensated, require the 752A to be returned to the factory for repair. This is due to the matching requirements for all four modules and the Bridge and Compensation board.

On pages 5-3 and 5-4, Table 5-1:

Change: A1IRESISTOR MODULES, MATCHED ASSEMBLY

IModule Exchange RecommendedI1

To: A1IRESISTOR MODULES, MATCHED ASSEMBLY

|Factory Maintenance Recommended|1

Delete: MP42I....

Change #2

On page 1-2, Table 1-2, under the POWER COEFFICIENT EFFECT ON RATIO***,

Change: 10:1 Ratio<0.05 ppm of input @ 100V
To: 10:1 Ratio<0.05 ppm of output @ 100V
Change: 100:1 Ratio<0.3 ppm of input @ 1000V
To: 100:1 Ratio<0.3 ppm of output @ 1000V

Change #3

On page 2-4, replace the note prior to paragraph 2-22, with:

Note

To minimize noise effects in 0.1 and 1V settings, the Null Detector is configured in opposite polarity.

Change #4

On page 2-4, replace Figure 2-2, with Figure 1.




Figure 1.

2

On page 2-6, replace Figures 2-4 and 2-5 with Figures 2 and 3 respectively.

Manual Supplement




Figure 2.

Note

If either the 752A or the KELVIN-VARLEY voltage dividers are not grounded through a rack-mounted case, provide an earth ground for both instruments.

Note

If the NULL DETECTOR is line operated, leave this shield connection back open. The purpose of the case ground connection shown in Figure 3 is to provide an earth ground to a battery operated NULL DETECTOR case. In this instance, the ground connection comes through the shield wires from the UUT. It is important this connection to earth ground be made for any battery operated Fluke 845AB NULL DETECTOR.

Manual Supplement 752A




Figure 3.

Change #5

On page 1-2, Table 1-2,

Change:	Input Voltage	To: Input Voltage
	100V	0 -100V
	1000V	0 -1000V

Change #6

On page 4-7, after paragraph 4-31, add the following procedure:

4-31a. LEAKAGE RESISTANCE TEST PROCEDURE

4-31b. Perform the following procedure to prevent ratio errors caused by leakage. It is recommeded that this procedure be done annually. Refer to Figure 4 for equipment connections.

4

Manual Supplement

1. Place the 752A on a sheet of dielectric. Use teflon insulated wires to connect the 1000V source to the 752A and 845AB. Connect a 1.1 megohm resistor across the 845AB input terminals to bring the input resistance to 1 megohm.

- 2. Connect the 1000V source to the 752A Input High binding post.
- 3. Connect the 845AB positive (+) input to the 752A Guard binding post.
- 4. Connect the 845AB negative (-) input to the 1000V source negative output binding post.
- 5. Set the 752A switches a follows:

Mode switch-----Set to "1000V (100:1)" position. Operate switch-----Set to "OPERATE" position.

- 6. Apply 1000V from the source.
- 7. The 845AB reading must be 0.5 mV or less to pass.
- 8. Set the source to standby and change the 845AB positive input lead from the 752A Guard binding post to the 752A Ground binding post.
- 9. Repeat steps 6 and 7.

752A




Figure 4. Equipment Connections For Leakage Resistance Test

752a_fig4.bmp

Change #7

On page 5-4,

Change: MP43INON-ACTIVATED FLUX SOLDERI713214I89536I713214I1

To: MP43ISOLDER,36IN LENGTH OF961480 FOR 752A |713222|89536|713222|1

5

Change #8 - 25693

On page 5-3, Table 5-1,

Delete: H9IWASHER,FLATI312538I89536I312538I1

On page 5-7, Figure 5-1, delete H9.

Manual Supplement 752A

Change #9 - 28667

On page 5-3, Table 5-1,

Add: H22IWASHER,FLAT,BRASS,#8,0.32 THK l631606l86928l5714-162-32l20 H23INUT,HEX,BR,8-32 l631614l73734l631614 l10 H24IB-P-WASHER l606293l89536l606293 l10

On page 5-5, Figure 5-1, add H22, H23, and H24 as shown in Figure 5.




Figure 5.

752a_fig5.bmp

Change #10 - 32973

On page 5-5, Figure 5-1, change the view of H4 as shown in Figure 6.

6 6/99

752A Manual Supplement




Figure 6.

752a-fig6.bmp

Change #11 - 33030

On page 5-4, Table 5-1,

Change S1ISWITCH ASSEMBLY,MODEI644963I89536I644963I1 To: S1ISWITCH ASSEMBLY,MODEI856174I89536I856174I1

Change: S2ISWITCH ASSEMBLY, CALIBRATE 1644971 189536 1644971 11 To: S2ISWITCH ASSEMBLY, CALIBRATE 1856166 189536 1856 1661 1

Change #12 - 33747

On page 5-3, Table 5-1,

Add: H21|WASHER,LOCK,INTERNAL|129957|78189|1220-05|1

On page 5-5, Figure 5-1, add H21 as shown in Figure 7.

6/99 7

Manual Supplement 752A




Figure 7.

8

752a_fig7.bmp

Change #13 - 38450

On pages 5-3 and 5-4, Table 5-1,

Change: MP15ITRIM,SIDE | 1642298189536164229812 | To: MP15ISIDE EXTRUSIONI859947189536185994712 | Change: MP16IINSERT,SIDE TRIMI642306189536164230611 | MP16IINSERT,SIDE TRIMI859942189536185994211 | Change: MP19IADHESIVE,SIDE TRIMI680850189536168085011 | MP19IADHESIVE,SIDE TRIMI698316122670169831611 | MP19IADHESIVE,SIDE TRIMI698316124670169831611 | MP19IADHESIVE,SIDE TRIMI69831611 | MP19IADHESIVE,SIDE TRIMI6981 | MP19IADHESIVE,SIDE TRIMI69811 | MP19IADHESIVE SIDE TRIMI6981 | MP19IADHESIVE SIDE SIDE SIDE S

Change #14

On page 1-2, under TEMPERATURE AND HUMIDITY,

Change: 95 +/-5% To: <95 80 +/-5% <80 75 +/-5% <75 45 +/-5% <45